

Airborne Science Program
Second Joint Airborne Science Sensor Integration Working Group Meeting
 NCAR Foothills Campus, Boulder, CO
 Bldg FL-0, Rm 2512
 February 3-4, 2009

PRELIMINARY AGENDA

Tuesday, 3 Feb

0830	Welcome and Introductions (All)
0845	Airborne Science Program and JASSIWG (Andy Roberts)
0900	Plan of Meeting (Marty) - Agenda - Approach (consider as a CDR for Phase A; PDR for Phase B)
0930	JASSIWG Status (Marty) - ATR distribution - Website - Overall approach and plan: Phase A, B, and C
1000	Short break
1015	Common Payload Data Package (CPDP) Review (Marty) - Rationale, purpose, web-form goal, known open issues, preliminary findings - Platform or Center brief (1-2) chart review and comment (ARC, DFRC, JSC, LaRC, WFF, GRC, NSERC) - Step through CDPD (note RIDs)
1200	Lunch
1300	CPDP Review Wrap Up (Marty) - CPDP RIDs Compilation RIDs review - Implementation issues: when, how, who
1330	Experimenter Handbook Format Review (Mike) -Intro (rationale, purpose, open issues, findings) - Platform or Center brief (1-2) chart review and comment (ARC, DFRC, JSC, LaRC, WFF, GRC, NSERC) - Step through EH (note RIDs) - Complete RID review - Implementation issues: when, how, who
1500	Short Break
1515	EH Format Review Wrap Up (Mike) - CPDP RIDs Compilation RIDs review - Implementation issues: when, how, who
1630	Summary for Day (All) - RIDs disposition - Open issues on Phase A products - Concurrence poll

Wednesday, 4 Feb

0830	Summary of previous day's activities (All)
0900	Overall Phase B general study approach (Mike)
0930	Preliminary Requirements Assessment (Mike) <ul style="list-style-type: none">- Preliminary results and concerns- Need for standard requirements engineering documentation- Discussion on how to proceed
1030	Short break
1045	WG Roundtable Discussion Related Topics (All)
1130	Summary and Next Steps (All)
1200	Adjourn

Directions for NCAR Foothills Campus:

HOTEL: Hilton Homewood Suites, 4950 Baseline Rd, Phone: 303-499-9922.

The Foothills campus is on Mitchell Lane in Boulder, CO.

Heading north on Foothills Parkway (157) from Baseline, take a right turn on Valmont.
Take the first left at the light on King's Ridge.
Follow for ~1/2 mile and turn right onto Mitchell Lane.
Follow to NCAR building and park on right in visitor parking.
Enter Foothills Lab 2 and sign in for the 'Aircraft Engineering' meeting at receptionist.

Meeting Room: FL-0, room 2512